

HID® FARGO® HDP®5000e

Windows Printer Driver
Release Notes

Driver version: 1.3.0.35
PLT-08105, A.2
August 2025



Copyright

© 2025 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, FARGO, and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

MIFARE, MIFARE Classic, MIFARE DESFire, MIFARE DESFire EV1, MIFARE Plus, and MIFARE Ultralight are registered trademarks of NXP B.V. and are used under license.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
August 2025	Release notes for version 1.3.0.35.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® HDP®5000e Windows Printer Driver version 1.3.0.35. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

Compatible operating systems:

- Windows 10 (32-bit and 64-bit)
- Windows 11 (64-bit)
- Windows Server 2016 (64-bit)
- Windows Server 2019 (64-bit)
- Windows Server 2022 (64-bit)

1.2 New features

- Added encrypted connections for trusted communication using TLS. (FSA-817)
- Added printer maintenance logs. (FSA-1228)

1.3 Resolved issues

- Resolved an issue with a spelling error on the **Magnetic Encoder Setup** tab. (FSA3-1886)
- Resolved an issue where the driver gives an extra prompt when closing. (FSA3-1835)

1.4 Known issues

- Driver displays the wrong reorder number of 084511 for YMCKK. The part number should show 084512 for YMCKK. (FSA3-1264)
- Driver does not display the **open door** prompt when the printer door is open. (FSA3-1263)
- Driver incorrectly shows the **Define Areas** in the preview window. (FSA3-980, TTP-16046)
- Driver does not display the laminator card jam prompt for a **laminator card jam Error#53**. (FSA3-1525)
- The Status Monitor does not display any lamination errors or warnings. (FSA3-1883)
- The printer certificate signing request generation occasionally fails. (FSA3-1909)



Revision history

Date	Description	Revision
August 2025	Release notes for version 1.3.0.35.	A.2
April 2025	Release notes for version 1.2.0.30.	A.1
January 2025	Initial release.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2025 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-08105, Rev. A.2

Part of ASSA ABLOY